

## DISTRIBUTION POLE FALLS ON BUSY ROADWAY

### NEW SOUTH CREATES ACCESS FOR COMED WITHIN HOURS OF RECEIVING THE CALL IN ILLINOIS

At 4:30 a.m. on the 4th of July, a distribution pole fell onto a busy roadway in McHenry, IL and within 30 minutes of the pole falling, NEW SOUTH received the call from ComEd.

After receiving the call at 5:00 a.m., a NEW SOUTH account manager inspected the site to determine access needs. The site evaluation revealed wet conditions, so the account manager coordinated the delivery of heavy-duty 5-ply, 8x14 access mats to the site.

By 7:30 a.m NEW SOUTH had crews and mats on site being installed and traffic control covered to provide access for ComEd to restore the distribution pole safely and in a timely manner.



#### PROJECT STATS

**72**

##### MATS

used to complete project

**1**

##### DAY

project duration

**1**





##### MAT TYPE

5-Ply Mat

**5**

##### PERSON CREW

1 Account Manager, 1 Project Manager, 2 Laborers for traffic control, 1 Operator for Skid Loader

-  Access Matting
-  ComEd
-  McHenry, IL
-  [www.newsouthmat.com](http://www.newsouthmat.com)

#### CHALLENGES

- Time
- Traffic
- Water



**LET'S JOIN FORCES.**

[www.newsouthmat.com](http://www.newsouthmat.com)

866-922-6287